

From the guys who brought you the world's best tape recorders... The world's newest and finest receiver.

Take a second look and you'll begin to see some of the things that make this receiver extraordinary. Like two tuning meters... three tape facilities... eight function-indicator lights. All of which do more than meets the eye.

That left-hand meter is a field-strength indicator when you're tuning FM. Pull out the speaker-selector knob and it becomes a power effect indicator—a built-in early warning system that will avert amplifier clipping and speaker overload.

Tapes 1 and 2 control standard rear-panel jacks for two decks—reel-to-reel, cassette, cartridge—so you can copy and convert as well as play and record. Tape 3 is a typical Tandberg

touch. It's jacked into a preamp circuit that lets you use the amplifier controls to modify the output signal. With Tape 3, you can tone down, brighten up, boost and rebalance worn discs and imperfect tapes when you re-record.

As for the pilot lamps, they're the visible indicator of eight function controls hidden under a flip-down cover. Two scratch/hiss filters for moderate or extreme high-frequency attenuation, rumble filter, loudness contour, Tape-3 preamp, mono left, mono right, and stereo.

What meets the ear in the TR1020 comes from the same no-compromise

electronics that have made Tandberg tape recorders *the* industry standard.

To cite just a few points, there's the true complementary output stages, a MOSFET front end for both AM and FM, separate power supplies, fully encapsulated electronic tuning, FM sensitivity typically 1.7 uV, and a capture ratio of 1.8 dB.

In sum, the TR1020 is pure Tandberg. An AM/FM stereo receiver that delivers about \$600 worth of performance for \$429.90.

Including the hardwood cabinet.

Don't just look at it. Look into it. With your nearest Tandberg dealer.



TANDBERG TR1020

When you make the finest tape decks in the world, you don't settle for second best in anything.
TANDBERG OF AMERICA, INC., 8 THIRD AVENUE, PELHAM, NEW YORK 10803

Check No. 53 on Reader Service Card